

UNITED STATES COMMISSION
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
10079
NEW MEXICO 88240

FE-
re-

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
POL PROPERTIES, INC.

3. ADDRESS OF OPERATOR
P. O. Box 9769, Fort Worth, Texas 76102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2063' FNL & 841' FEL of Section (SE 1/4 NE 4/4)
(Unit "H")

14. PERMIT NO. ---

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3825' G.L.

5. LEASE DESIGNATION AND SERIAL NO.
NM-24166

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
SPRINKLE FEDERAL

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Scharb - Bone Springs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 9-19S-35E

12. COUNTY OR PARISH
Lea

13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

16. NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Casing Report</u> <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well on 5-28-83.

In a 17 1/2" hole, ran 350' of 13 3/8" (48#, K-55) casing and cemented with 350 sacks (Class "C" w/2% calcium chloride & 1/4# flocele/sack). Plug down at 1:05 AM on 5-29-83. Circulated 85 sacks.

In a 11" hole, ran 3575' of 8 5/8" (0-120.73'/32#, K-55; 120.73'-2295.03'/24#, K-55; 2295.03'-3575.45'/32#, K-55) casing and cemented with 1700 sacks (1400 sx Halliburton Lite w/15# salt and 1/4# flocele/sack and 300 sx neat "C"). Plug down at noon on 6-3-83. Circulated 336 sacks.

In a 7 7/8" hole, ran 10770' of 5 1/2" (17#, N-80) casing and cemented with 650 sacks (Halliburton 50-50 Pozmix w/2% Gel, 6/10% Halad-22, 3# KCL/sack). Plug down at 7:40 PM on 6-24-83.

RECEIVED

AUG 4 1983

OIL & GAS

18. I hereby certify that the foregoing is true and correct

ROSWELL, NEW MEXICO

SIGNED James A. Knauf
(This space for Federal or State office use)

TITLE Agent

DATE July 29, 1983

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

AUG 8 1983

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO

RECEIVED

AUG 9 1983

C.C.D.
HOBBS OFFICE