

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P.O. BOX 2088
SANTA FE, NEW MEXICO 87501

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-740

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Mesa Operating Limited Partnership 3. Address of Operator P.O. Box 2009, Amarillo, Texas 79189 4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 19S RANGE 35E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3844' GR	7. Unit Agreement Name 8. Farm or Lease Name VACUUM STATE 9. Well No. #3 10. Field and Pool, or Wildcat Scharb Bone Springs 12. County Lea
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up pulling unit 0900 hrs 5/18/87 and P&A'd well as follows:

Set CIBP @ 8900'; displaced 5 1/2" casing w/210 bbls 10 ppg mud laden fluid; spotted 35' Class "C" cement on top of CIBP. PBTB 8865'. Cut 5 1/2" casing @ 6955', LD 167 jts 5 1/2" B & C casing. Displaced hole w/65 bbls 10 ppg mud laden fluid. Set 35 sx Class "C" cement plug from 7005' - 6905'; Set 40 sx Class "C" cement plug from 5200' - 5300' (top of San Andres); set 40 sx Class "C" cement plug from 3988' - 4088' (8 5/8" shoe plug); tag top plug # 3 (8 5/8" shoe plug) @ 3982' (106' fill). Set 30 sx Class "C" cement plug from 450' - 550' (13 3/8" shoe plug); set 10 sx Class "C" cement plug from surface to 35' cut off wellhead; installed dry hole marker; clean location. Well P&A 5/27/87. R. A. Sadler from NMOCD on location to witness plugging.

xc: NMOCD-H (0+5), Prod Rcds, Reg, Land, Expl., Acctg, Partners

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Carey Cummings</u>	TITLE <u>Regulatory Analyst</u>	DATE <u>5/28/87</u>
APPROVED BY <u>R. A. Sadler</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 1 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
MAY 21 1997
FBI
HONOLULU OFFICE