

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-28239
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-6977

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		7. Lease Name or Unit Agreement Name:  Aztec Dos State
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		
2. Name of Operator Lynx Petroleum Consultants, Inc.	8. Well No. #1	
3. Address of Operator P.O. Box 1708 Hobbs, NM 88241	9. Pool name or Wildcat Young Bone Spring, N.	
4. Well Location  Unit Letter <u>L</u> : <u>2080</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line  Section <u>2</u> Township <u>18S</u> Range <u>32E</u> NMPM County <u>Lea</u>		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3871.6' GR		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<p><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>		<p><b>SUBSEQUENT REPORT OF:</b></p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	
--	--	---	--

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/30/01

1. Set a C.I.B.P. @ 8250' on wireline and dump bailed 35' of cement on top. Tagged plug with wireline at 8215'.
2. Set a C.I.B.P. @ 6600' on wireline and dump bailed 35' of cement on top.
3. Circulated the hole with 9.5 ppg brine gel mud.
4. Cut and pulled the 4 1/2" casing at 4505'.
5. Spotted 50 sxs cement at 4550'. Tag cement at 4398'.
6. Spotted 30 sxs cement at 1250'-1150'.
7. Spotted 30 sxs cement at 705'. Tag cement at 593'.
8. Spotted 10 sxs cement surface plug. Installed dryhole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marc Wise TITLE President DATE 5/3/01

Type or print name Marc Wise Telephone No. 392-6950

(This space for State use)

APPROVED BY [Signature] TITLE [Signature] DATE 10-18-01

Conditions of approval, if any:

GWW

