

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
~~B-3385~~ ~~E-8712~~  
~~B-3385~~ ~~E-8712~~

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator CASA PETROLEUM, INC.	8. Farm or Lease Name Gulf State
3. Address of Operator 105 North Sixth Street, Artesia, New Mex.c 88210	9. Well No. 1
4. Location of Well UNIT LETTER B 990' FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 17S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Vacuum Grayburg San
15. Elevation (Show whether DF, RT, GR, etc.) 4061.0 G.L.	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/> Perforate & Treat
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop work) SEE RULE 1703.

Perforate from 4994-5008- 15S/ 4705-25 - 20S/ 4448-4642 - 34S  
9/13 Acidize perfs from 4705-25 with 2000 gal 15% NEFE  
9/12 Acidize perfs from 4994-5008 with 2000 gal 15% NEFE  
9/14 Acidize perfs from 4448-4642 with 3000 gal. 15% NEFE and fraced  
with 40,000 gal gel water and 40,000 # 20/40 sand  
9/16 Hang well on pump/ pumping back load water.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ranger C. Karr TITLE President DATE 9/27/83

RANGER C. KARR  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE SEP 30 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
SEP 29 1983  
C. C. HOBBS  
HOBBS OFFICE