

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2086
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-7

30. Indicate Type of Lease
State ☒ Fee ☐

31. State Oil & Gas Lease No.

L.G. 1630

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPERATE OR PLUG AREA TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator

Gulf Oil Corp.

3. Address of Operator

P. O. Box 670, Hobbs, NM 88240

4. Location of Well

UNIT LETTER G 1830 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 16 TOWNSHIP 19S RANGE 35E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

Lea "TZ" State

9. Well No.

3

10. Name and Loc. of Landcat

Charles Spring

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Post up prod eqpt. Oil out CIBP. Clean out to 9730'. Set cmt
ret @ 9660', test thg 3000 psi. Pump 100.24 cmt. Sq. to 1000 psi
above pump-in press. Oil cmt ret + cmt. Perf 9670-74'
w/2) JH. Acq. G/H up prod eqpt.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R D Pite

TITLE AREA ENGINEER

DATE 4-11-85

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT 1 SUPERVISOR

APR 15 1985

RECEIVED

APR 12 1985

U.S. DEPT. OF JUSTICE
HUMAN RIGHTS OFFICE