Submit 3 Copies To Appropriate District		State of New Mexico, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.		
Office District I	nergy, Minerals					
1625 N. French Dr., Hobbs, NM 87240				f		
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION				30 – 025 – 28434		
District III 2040 South Pacheco			5. Inc	5. Indicate Type of Lease STATE ■ FEE □		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505				tate Oil & Gas I		-
District IV 2040 South Pacheco, Santa Fe, NM 87505					6002	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name:		
PROPOSALS.)				B Lee State		
Type of Well: Oil Well						ļ
2. Name of Operator				Vell No.		\neg
Nadel and Gussman Permian, L.L.C. OGRID # 155615				7		Ì
3. Address of Operator				9. Pool name or Wildcat		
601 N Marienfeld, Suite 508, Midland, Texas 79701				Scharb (Bone Springs)		
				~ ~ ~ ~ ~		_
4. Well Location						
Unit Letter <u>H</u> :	1980' feet from	the <u>North</u>	line and 660'	feet from the	e <u>East</u> line	
Section 5	Township 19 - S	Range	35 - E NMPM	Lea	a County	
1. Elevation (Show whether DR, RKB, RT, GR, etc.)						
		' GL,	3907' KB			
11 Check A	Appropriate Box to It	ndicate Nati	re of Notice, Repor	t or Other Da	ta	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				□ A	LTERING CASING	
PERFORM REMEDIAL WORK) LOO AND NOMINEO					
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	OPNS. P	PLUG AND ABANDONMENT	
COMPLETION CEMENT JOB				Ш		
OTHER Describe proposed or completed operation	(0)	<u> </u>	OTHER	ated date of starting	any proposed work) SF	E
Request to Temporary Aba	ındon Well:	-				
08-27-01 MIRU Basic Well	Services. Pulled r	ods and pu	ımp and used then	n in the McC	lellan A #2.	
1. MIRU. Bleed any press	ure off of the tubing	g. Release	the TAC at 9297. P	OH with ho	M39 30,32	
2 PH wireline Set 51/3" C	IRP at 9450' and ca	n with 35's	cement by bailer.	2522	2	
Request to Temporary Abandon Well: 08-27-01 MIRU Basic Well Services. Pulled rods and pump and used them in the McClellan A #2. 1. MIRU. Bleed any pressure off of the tubing. Release the TAC at 9297. POH with a result of the state of the						
3. Load casing with innib	ited water. Test to	oud partor	ov minuces.	3212		
4. Request TA status whi	le we review uphol	e potential	•	Cor	· 3/-	
I hereby certify that the information	on above is true and com	plete to the be	est of my knowledge and	belief. 1919	HUSVE Y	
SIGNATURE AND THE SIGNATURE			Operations Engine	eer DA	TE 2-21-0	<u> </u>
Type or print name Robert M	IcNaughton		Telephone No.	915 – 682 -	- 4429	
(This space for State use)	•					
APPPROVED BY		. THLE:	(()		DATE	
WELLKOARD DI		aligorad i d Livinis	5002 SAAP	LCVI	PATE 2 8 2002	
Conditions of approval, if any:	——————————————————————————————————————	e verkentet	cative hyetapp make	· · · · · · · · · · · · · · · · · · ·	9 4002	_

JADEL AND GUSSMAN PERMIA.

B LEE STATE No. 7

1980' FNL, 660' FEL, Unit H, Sec 5, 19S, 35E, Lea County, NM API # 30-025-28434

Elev: 3893'.5 GL, 3906.5' KB

Current Status - TA

13-3/8", 54.5#, K-55 @ 450' 450 sx, circulated 17-1/2" hole


8-5/8", 32#, K-55 @ 4000' 1775 sx, circulated 11" hole

DV Tool @ 9005' 1150 sx, TOC @ 2400' by T.S.

5-1/2", 15.5/17/20#, K55 / L80 @ 10,825' 400 sx, TOC @ ~9335' by CBL 7-7/8" Hole

PBTD @ 9,415'

TD @ 10,825'



Bone Springs Perfs: 9490' - 9594' @ 2 SPF, 66'- 132 holes

Baker RBP at 9601'

Bone Springs Perfs: 9608' - 9660' @ 2 SPF, 32'- 64 holes, 5000 gals 15% CIBP @ 10,300' w/ 35' cement

Wolfcamp Perfs: 10,448' - 10,611' @ 2 SPF, 110 holes, 10K 15% NEFE

