

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
LG 1631

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-103) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-
2. Name of Operator Shiff Oil Corp.
3. Address of Operator P.O. Box 670, Hobbs, NM 88240
4. Location of well
UNIT LETTER J 2080 FEET FROM THE South LINE AND 2070 FEET FROM
THE East LINE, SECTION 16 TOWNSHIP 19S RANGE 35E N.M.P.M.
10. Field and Pool, or Wildcat Charles Bore
12. County Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3781' @ L

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propos work) SEE RULE 1103.

Incarnado
Spud 17 1/2" hole 7:50 A.M., 11-17-83. TD 450' @ 12:30 P.M., 11-17-83. RLL + ran
10 jts 1 3/8" 11-40 ST+C, set @ 450'. Cmt w/ 500-24 @ "C" 2% CaCl.
Plg dwn 6:00 P.M., 11-17-83. Circ 1.35-24. Del cmt. Test asy
1000 psi OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE AREA DRILL SUPT DATE 11-29-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE DEC 1 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
NOV 30 1983
HODGS OFFICE