

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator TXO Production Corp.		8. Farm or Lease Name Hooper "A"
3. Address of Operator 900 Wilco Bldg. Midland, TX 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1840</u> FEET FROM THE <u>South</u> LINE AND <u>1840</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>19-S</u> RANGE <u>35-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Scarb (Bone Springs)
15. Elevation (Show whether DF, RT, GR, etc.)		12. County lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-30-85 Removed W H. Installed BOP. Rlsd prk & TOH w/2 3/8" tbq. TIH w/CIBP & set @9450. 35' cmt on top CIBP.  
8-31-85 TIH and cut csg @7250.  
9-1-85 thru Shut-in for Sunday & Holiday.  
9-2-85  
9-3-85 TIH w/ 2 3/8" tbq. Set 35sx "C" 2% CaCl plug @7303. Waited 2 1/2hrs. TIH Tag TOC @7189. Set 35sx "C" neat plug @5218. Set 35sx "C" neat plug @4548 Set 35sx "C" 2% CaCl plug @3930  
9-4-85 Tagged cmt @3826. Set 35sx "C" neat plug @1906. Set 35sx "C" neat plug @458. Set 10sx "C" neat plug @surface. Plug & install dry hole mkr. Well P & A'd

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Celicia Henderson

TITLE Engr. Asst.

DATE 9-5-95

APPROVED BY Reynold M. [Signature]  
CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR

DATE APR 1 - 1986

RECEIVED  
SEP -9 1985  
HUBBARD OFFICE