

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TXO Production Corp.	8. Farm or Lease Name Hooper A
3. Address of Operator 900 Wilco Bldg Midland TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1840</u> FEET FROM THE <u>south</u> LINE AND <u>1840</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>19-S</u> RANGE <u>35-E</u> NMMP.	10. Field and Pool, or Wildcat Scharb Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods, tbg, pmp OOH

Perforate Upper Bone Springs: 9512-14 1 spf
9519-20 1 spf
9540-60 1 sp 2 ft
9605-18 1 spr
9646-52 1 spf
9658-75 1 spf 51 total holes

Set RBP via wireline @ 9750'
RIH w/tbg, pkr. Set pkr @9480
Acidize via tbg
Test Retrieve RBP
Place well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lane Guffy TITLE Production Engineer DATE 9-4-84

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE SEP 6 1984

Q27

Q28

Q29