

C.L. CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator The Superior Oil Company		8. Farm or Lease Name Mescalero Ridge
3. Address of Operator P.O. Box 3901, Midland, Texas 79702		9. Well No. 8
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> NMPM.		10. Field and Pool, or Wildcat Scharb (Bone Spring)
15. Elevation (Show whether DF, RT, GR, etc.) 3864.8' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

8-5/8" Casing Detail 2-15-84 thru 2-17-84

1. Ran 105 jts 8-5/8" 24# K-55 ST&C csg, set @ 4100', cmt'd w/1800 sxs Pacesetter Lite (wt 12.4#, yield 1.98). Tailed in w/800 sxs Class C cmt w/2% Ca cl (wt 14.8#, yield 1.32.) Plug down @ 0900 hrs 2-16-84 w/1500#. Full returns. Did not circ cmt.
2. Ran temp svy, found TOC @ 2200'.
3. Tested equip, etc.
4. Drld cmt @ 1500 hrs 2-17-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED G. E. Tate TITLE Division Operations Supt. DATE 3-20-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 21 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 21 1984

O.C.D.
HOBBS OFFICE