

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-72

NO. OF COPIES DESIRED	
DISTRIBUTION	
DATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5. Indicate Type of Lease	
State ☐	Fee ☐
6. State Oil & Gas Lease No.	
750469	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER2. Name of Operator
TEXACO Producing Inc.3. Address of Operator
P.O. Box 728, Hobbs, New Mexico 332404. Location of Well
WELL LETTER K 2310 FEET FROM THE South LINE AND 2310 FEET FROM
THE West LINE, SECTION 10 TOWNSHIP 19S RANGE 35E NMPM.5. Elevation (Show whether DF, RT, GR, etc.)
3842.0 GL12. County
LeaCheck Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:6. ☐ REMEDIAL WORK
☐ GRABILY ABANDON
☐ OR ALTER CASING7. ☐ PLUG AND ABANDON
☐ CHANGE PLANS8. ☒ REMEDIAL WORK
☐ COMMENCE DRILLING OPNS.
☐ CASING TEST AND CEMENT JOB
OTHER9. ☐ ALTERING CASING
☐ PLUG AND ABANDONMENT
☐

10. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pulled tbq. and pkr.
2. Set RBP and test to 1500#. OK. Spotted w/150 gal. 10% acetic acid, 10,500-10,400'.
3. Set pkr. Perfed 2 SPF 10,445 to 10,487 (58 holes).
4. Acidized 10,445-487' w/7000 gal. gelled 15% NEFE w/74 ball sealers.
5. POH w/pkr. and RBP.
6. Ran 22 jts. 2 7/8" tbq. TA and 3/8 jts. 2 7/8" tbq.
7. Ran production equipment and test well and evaluate.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CO W. B. Loh TITLE Dist. Con. Mgr. DATE 6/26/85
JUL - 2 1985
TITLE _____ DATE _____