

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Aramita, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28662
1. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	7. Lease Name or Unit Agreement Name Lea "TZ" State
2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 5
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Foot name or Wildcat Scharb/Bone <i>Wolfcamp, etc.</i>
4. Well Location Unit Letter <u>H</u> : <u>1790</u> Feet From The <u>North</u> Line and <u>900</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>19S</u> Range <u>35E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTIFY NM OCD 24 HRS PRIOR TO START OF P&A OPERATIONS @ 393-6161
MIRU PU TIH W/OE TBG SPOT P&A MUD F 10555 TO 6500±, RU WL CO. & RUN FREE POINT INDICATOR
SET CIBP @ 9000' CAP W/35' CMT TST CSG TO 500 PSI
CUT & PULL 5 1/2" CSG AS REQUIRED (INSTALL THREAD PROTECTORS)
SET 200' CMT PLUG ACROSS 5 1/2" CSG STUB (100' INSIDE & 100' OUTSIDE) Tag
SET 200' CMT PLUG ACROSS SAN ANDRES F 5324' TO 5124'
SET 200' CMT PLUG ACROSS 8 5/8" CSG SHOE F 4250 TO 4050 Tag
SET 200' CMT PLUG ACROSS TOP OF ANHY F 1913 TO 1713'
SET 60' CMT PLUG FROM 60' TO SURFACE
INSTALL DRY HOLE MARKER
CHANGE STATUS TO PLUG & ABANDONED
**P&A MUD TO BE PLACED BETWEEN ALL CMT PLUGS

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

***SEE ATTACHED SHEET FOR FORMATION TOPS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins 8/10/90 TITLE Staff Drlg. Engr. DATE 8-10-90

TYPE OR PRINT NAME M. E. Akins

TELEPHONE NO. 393-4121

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FORMATION TOPS FOR LEA "TZ" STATE #5

T/ANHY	-	1813'
BASE SALT	-	3204'
T/YATES	-	3368'
T/7 RIVERS	-	3872'
T/QUEEN	-	4615'
T/GRAYBURG	-	4910'
T/SAN ANDRES	-	5224'
T/DELAWARE	-	5593'
T/BONE SPRING	-	7791'
T/WOLFCAMP	-	10676'