

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATES
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 42 R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM-57285

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

MorOilCo, Inc.

3. ADDRESS OF OPERATOR

P.O. Drawer I Artesia, NM 88211-0269

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330' FNL 330' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3694.9 GR

Unit Letter A

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Stivason Federal

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Pearl Queen

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

33-19-34

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Convert to Oil Well

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

6/15/87 TOH with rods & pump. TOH with packer. TIH with on & off tool. Circulate sand on top of packer at 4200'. Latch on to packer and TOH. TIH with packer & tubing and prepare to run rods. Prepare to test Queen perforations 4511' - 14', 4528' - 32'. Shut down.

6/06/87 TIH with 160 3/4" rods, 1 - 4', 1 - 8', 3 - 2', subs. Hang well on. Rig down.

18. I hereby certify that the foregoing is true and correct

SIGNED

Frank Meyer

TITLE Operator

DATE 6/15/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAY 27 1988

SJS

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO