

Form 1-311
May 1983

N. M. OIL CONS. COMMISSION

P. O. BOX 1980

HOBBS, NEW MEXICO 88240

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-11121.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☒ GAS ☐ WELL ☐ OTHER ☒ *Dry*

2. NAME OF OPERATOR
Gulf Oil Corporation

3. ADDRESS OF OPERATOR
P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Print location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2310' FAK + 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, BT, CR, etc.)
3912' GL

5. LEASE DESIGNATION AND SERIAL NO.
NM 40456

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. LAND OR LEASE NAME
Indes Box Springs

9. WELL NO.

10. FIELD AND TOWN, OR WILDCAT

11. SEC., T., R., M., OR ALIAS
SURVEY OR AREA
Sec 1-T1PS-R32E

12. COUNTY OR PARISH 13. STATE
Lea NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

☐
☐
☐
☐
☐

PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANS

☐
☐
☐
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

☐
☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

☐
☐
☒
☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD 9200' 10:15 P.M. 10-23-84. Log. Set following plugs per Bob Pitcock (R27M): 8400'-8310' (150"-50.24), 7800'-7650' (150"-50.24), 6150'-6000' (150"-125.24), 5400'-5250' (150"-75.24), 4700'-4600' (100"-50.24), 3850'-3750' (100"-70.24). Log plug #6 @ 3700'. Set plug @ 550'-450' (30.24). Set 50' surf plug at 15.24 cmt. Install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED *Charles S. Denson*

TITLE *Area Engineer*

DATE *11-30-84*

(This space for Federal or State office use)
Orig: Sgd. Charles S. Denson

APPROVED BY *Area Manager*
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE *9-9-85*

nm

RECEIVED

SEP 11 1985

G.C.I.
HOBBS OFFICE