1.46

## P. O. TO THE TOTAL CONTROL OF THE STATE STORES, THEY THE TOTAL CONTROL OF THE STATE STORES. DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY	NM-9018 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Young Deep Unit 8. FARM OR LEASE NAME
1. oil gas other	9. WELL NO.
2. NAME OF OPERATOR -	15
Harvey E. Yates Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	North Young Bone Springs
P. O. Box 1933, Roswell, New Mexico 88201 4. LOCATION OF WELL (REPORT LOCATION CLEARLY See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	Sec. 9, T-18S, R-32E
AT SURFACE: 1650' FNL & 1980' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH: Same	Lea NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3830' GL
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* Spud well (other) RIH w/csg & press test.  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertiner Spud well @ 5:30 p.m. 3/9/85. RIH w/13 jts 13 3/8" 54.5# J-55 ST&C csg & set & 200 sxs class "C". Circ 60 sxs to pit. WOC 15" - held o.k.	rectionally drilled, give subsurface locations and to this work.)*  @ 537'. Cmt w/200 sxs lite weigh:
	ms
Subsurface Safety Valve: Manufand Type  18. I hereby certify that the foregoing is true and correct  SIGNED TITLE Reservoir Eng	Set @Ft.
(This space for Federal or State off	ide (ise)
APPROVED BY CONDITIONS OF APPROVAL IF ANY CONDITIONS OF APPROVAL IF ANY CONDITIONS	DATE
MAR 13 (965	

WAR 10 1085