

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-29160</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name BRIDGES STATE
8. Well No. 193
9. Pool name or Wildcat Vacuum (G-SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Mobil Producing TX & N.M. Inc.
3. Address of Operator Mobil Exploration & Producing U.S. Inc. P.O. Box 633 Midland, TX 79702	4. Well Location Unit Letter <u>G</u> : <u>1427</u> Feet From The <u>North</u> Line and <u>2554</u> Feet From The <u>East</u> Line Section <u>23</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>Lea</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) MIRU WO Unit. NU BOP Test.
 - 2.) Set CIBP @ 4340' + 35' cmt.
 - 3.) Circ well w/9.0 ppg gelled brine.
 - 4.) Set 50' cmt plug 3720 - 3770
 - 5.) Set 50' cmt plug 2675 - 2725
 - 6.) Perf 1675 - 77 4SPF, set retainer @ 1600'. Circ between 5 1/2 & 8 5/8 csg w/200x cmt.
 - 7.) Set 100' plug @ surface, cut csg 3' below ground, weld on P & A marker.
- Procedure discussed w/Paul Koats (NMOCD) on 4-12-89

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley Todd TITLE AS AGENT FOR MOBIL PRODUCING TX & N.M. INC. DATE 8-23-89
TYPE OR PRINT NAME Shirley Todd TELEPHONE NO. (915) 688-2585

ORIGINAL SIGNED BY JERRY SEXTON
(This space for State Use) DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

AUG 25 1989

RECEIVED

AUG 24 1989

OCD
HOBBS OFFICE