

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OFFERED TO REEVE	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

3a. Indicate Type of Lease	
State ☒	Fee ☐
3. State Oil & Gas Lease No.	
LG 1784	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator Harvey E. Yates Company		8. Name of Lessee Name Amoco East 2 State
3. Address of Operator P.O. box 1933, Roswell, New Mexico 88202		9. Well No. 4
4. Location of Well UNIT LETTER <u>DJ</u> 660' FEET FROM THE South LINE AND 1980' FEET FROM THE East LINE, SECTION 2 TOWNSHIP 18S RANGE 32E NMPM.		10. Field and Pool, or Wildcat North Young Bone Spring
11. Elevation (Show whether DF, RT, GR, etc.) 3877.7 GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-18-87 Set CIBP @ 8600'.
12-19-87 Abrasajet 2 cuts @ 8444' and wash w/350 gals 20% SRA.
12-20-87 Spot 100 gals 20% SRA over cuts. Unable to break down. Rev. out & respot w/4 bbl. 20% SRA.
12-22-87 Abrasajet 2 cuts @ 8444 & jet w/500 gals 20% SRA
12-23-87 Spot 200 gals 20% SRA across cuts. Break down cuts & follow w/1300 gals same acid.
12-29-87 Acidize w/5000 gals 20% SRA + 5000 gal overflush & N2.
12-31-87 Perf. 8397 - 8410', (13' - 27 holes)
1-1-88 Spot 250 gal 20% MSR-150 across perfs.
1-5-88 Acidize w/2500 gal SRA
1-6-88 Acidize w/10,000 gals 20% MSR-100. Swab to test.
1-15-88 SI well for evaluation.

skh
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Manager/Engineer DATE February 9, 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 11 1988

OCD
HOBBS OFFICE