

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

EXPIRES AUGUST 1, 1985  
LEASE DESIGNATION AND SERIAL NO.

NM-59044

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a depth of 100 feet or more. Use "APPLICATION FOR PERMIT TO DRILL" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Cavalcade Oil Corporation		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR P. O. Box 16187, Lubbock, TX 79490		8. FARM OR LEASE NAME Cavalcade "21" Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FSL & 1800' FEL		9. WELL NO. 5	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Undesignated	
15. ELEVATIONS (Show whether OF, ST, OR, etc.) 3754.4 GR		11. SEC., T., R., M., OR S.E. AND SURVEY OR AREA 2/ -2,18S,32E	
		12. COUNTY OR PARISH Lea	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
MULTIPLE COMPLETS	<input checked="" type="checkbox"/>		
ABANDON*	<input type="checkbox"/>		
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Prepare to plug and abandon the Cavalcade "21" Federal No. 1 well per BLM requirements.

1st plug - Set @ 4150' with 40 sacks cement.

2nd plug - Set @ 1500' with 90 sacks cement.

3rd plug - Set @ 465' with 25 sacks cement.

4th plug - Set @ surface with 10 sacks. Dry hole markers will be installed & well abandoned

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Vice President - Land DATE 01/31/86

This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 26 86  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side