

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

API #30-025-29287

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL <input checked="" type="checkbox"/> WELL GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator SHELL WESTERN E&P INC.		8. Farm or Lease Name MCINTOSH	
3. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001		9. Well No. 1	
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1980</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>21</u> TOWNSHIP <u>19-S</u> RANGE <u>35-E</u> N.M.P.M.		10. Field and Pool, or Wildcat UNDESIGNATED	
15. Elevation (Show whether DF, RT, GR, etc.) 3782.3' GL		12. County LEA	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNG. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-21 to 7-22-85: Displaced hole w/9.1# mud. Pumped total of 202 sx Class "H" Neat cmt @ the following intervals: 10,700' - 10,600' (30 sx), 7870' - 7770' (47 sx), 4620' - 4520' (47 sx), 4050' - 3950' (38 sx), 450' - 350' (30 sx), 3' - surface (10 sx). Cut off 20", 13-3/8" & 8-5/8" csg's 3' below ground level and welded on dry hole marker. Filled pits, cleaned and leveled location. Well is now plugged and abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. J. FORE</u>	TITLE <u>SUPERVISOR REG. &amp; PERMITTING</u>	DATE <u>AUGUST 20, 1985</u>
APPROVED BY <u>R. A. ...</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>OCT 28 1986</u>

RECEIVED

AUG 22 1985

POST OFFICE