

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29430
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520-1
7. Lease Name or Unit Agreement Name NORTH VACUUM ABO UNIT
8. Well No. 286
9. Pool name or Wildcat VACUUM ABO NORTH

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Mobil Producing TX & NM Inc.*	
3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for Mobil Producing TX & NM Inc.; P.O. Box 633, Midland, TX 79702	
4. Well Location Unit Letter <u>O</u> : <u>540</u> Feet From The <u>SOUTH</u> Line and <u>1930</u> Feet From The <u>EAST</u> Line Section <u>26</u> Township <u>17S</u> Range <u>34E</u> NMPM LEA County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL=4016 FUD=KB (18' AGL)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU WO UNIT, POOH W/RODS & PUMP NU BOP, TEST. POOH W/TBG & TAC.
- ADD ABO PERFS: 8560-68, 8586-94; 8614-18, 8626-28, 8636-40' 2 SPF 62 HOLES.
- ACIDIZE ABO PERFS 8438-8640' W/4000 GAL CROSS-LINKED 15% HCL + 150 1.3 SP GR. RCBS.
- RIH W/RODS & PUMP & TBG & TAC. POP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley Todd TITLE Proration Analyst DATE 12-07-89
TYPE OR PRINT NAME SHIRLEY TODD TELEPHONE NO. 688-2585

(This space for State **ORIGINAL SIGNED BY JERRY SEXTON**
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 11 1989

RECEIVED

DEC 10 1989

OOD
HOBBS OFFICE