

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-29532
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	V-927
7. Lease Name or Unit Agreement Name	TIPPERARY 4 STATE
8. Well No.	2
9. Pool name or Wildcat	SHIPP STRAWN
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3786' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TIPPERARY OIL & GAS CORPORATION

3. Address of Operator
633 17th STREET, DENVER, CO 80202

4. Well Location
Unit Letter F : 1980 Feet From The NORTH Line and 2130 Feet From The WEST Line
Section 4 Township 17S Range 37E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE ATTACHED PROCEDURE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kent Keller TITLE ENGINEERING TECH DATE 12/13/99

TYPE OR PRINT NAME KENT KELLER TELEPHONE NO 303-293-9379

(This space for State Use)

APPROVED BY WILLIAMS TITLE SUPERVISOR DATE DEC 23 1999

CONDITIONS OF APPROVAL, IF ANY:

MD

12-14-99
AFE for P & A

Lease: TIPPERARY # 4-2

Project: PLUGGING & ABANDONMENT

COSTS:

WORKOVER RIG 48 HRS @ \$ 108.00/HR	 \$ 4,860.00
PUMP TRUCK FOR CEMENTING & CIRCULATING	 \$ 1,000.00
CLASS C NEAT CEMENT @ \$ 7.50/SACK (290)	 \$ 2,175.00
FRESH WATER, BRINE & GEL	 \$ 750.00
BACKHOE TO DIG & COVER PIT & CELLAR	 \$ 200.00
RENTAL ON BOP	 \$ 150.00
WELDER TO WELD ON & CUT OFF	 \$ 250.00
CASING CUT (2)	 \$ 1,200.00
PERFORATING	 \$ N/A
RENTALS	 \$ N/A
WIRELINE TRUCK TO SET CIBP	 \$ 1,000.00
Contingencies	 \$ 500.00
SUPERVISION(4 DAYS)	 \$ 1,120.00

	SUB-TOTAL \$ 13,529.00
LAND SURFACE RECLAMATION	 \$ 500.00

	EST. COST \$ 13,705.00

PROCEDURE:

1. MRU - POOH WITH RODS & TUBING
2. SET CIBP @ 5,050' W/35' CEMENT ON TOP
3. RIH W/TBG & CIR. 9.5# MUD
4. PULL 5 1/2" CASING AS DEEP AS POSSIBLE - 4300' +/-
5. SPOT 45 SXS @ STUB & TAG
6. SPOT 50 SXS @ 4216'-4116' & TAG
7. SPOT 35 SXS @ TOP OF SALT - 2200' +/-
8. PULL 8 5/8" CASING @ 1000' +/-
9. SPOT 65 SXS @ STUB & TAG
10. SPOT 85 SXS @ 464'-364'
11. SPOT 10 SXS @ 30' TO SURFACE - INSTALL DRY HOLE MARKER
12. RIG DOWN - CUT OFF WELLHEAD, ANCHORS & LEVEL PIT & CELLAR