

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Bureau of Geology, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-29541

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Humble City ADH

8. Well No.

1

9. Pool name or Wildcat

Humble City Yeso

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line

Section 11 Township 17S Range 37E NMPM 1 County Lea

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3741.1' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONTINUED FROM PREVIOUS PAGE:

Pumped 220 bbls fresh water and worked casing. Rigged up casing equipment. POOH with 5-1/2" casing. Shut down due to weather. NOTE: Notified Jack w/OCD-Hobbs on casing cut. 6-29-7-1-96 - POOH with rest of 5-1/2" casing. Rigged down casing equipment. TIH with 2-7/8" tubing to 4575'. Mixed and pumped 50 sacks Class C 2% CaCl2 from 4575-4426'. POOH with tubing to 2500'. WOC 3-1/2 hours. TIH with tubing and tagged top of cement at 4389'. POOH with tubing to 2425'. Shut down for night. NOTE: Notified Jack w/OCD-Hobbs on cement plugs. 7-2-96 - Mixed and pumped 40 sacks Class C cement from 2425-2325' (in 8-5/8" casing). POOH with tubing to 495'. Mixed and pumped 40 sacks Class "C" cement from 495-395' (in 8-5/8" casing). POOH with tubing to 50'. Mixed and pumped 15 sacks Class C cement from 50' to surface. POOH with tubing. Nipped down BOP and spool. Rigged down pulling unit. Cleaned location. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 7-1-96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE July 2, 1996

TYPE OR PRINT NAME Rusty Klein

TELEPHONE NO. 505/748-147

(This space for State Use)

APPROVED BY Tamy M. Lipp TITLE _____ DATE NOV 06 1996

CONDITIONS OF APPROVAL, IF ANY: