

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ For ☐

5. State Oil & Gas Lease No.  
B-1565

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - M" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name New Mexico "BM" State
3. Address of Operator PO Box 728, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of well UNIT LETTER <u>O</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>1652</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>17S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Double A Abo Lower
15. Elevation (Show whether DF, RT, GR, etc.) 3875.6' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU, 08/08/87. Pull rods, pump and tubing.
- 2) Perf lower Double A Abo 9236'-40', 9258'-64', 9268'-76' (2 SPF, 42 holes).
- 3) GIH with 3 1/2" workstring and packer to 7400'.
- 4) Frac perfs 9236'-9342' with 60,000 gals. 40# cross-linked gelled 2% KCL and 120,000 lb. 20/40 sand in 6 stages with 1 through 5 ppg sand.
- 5) GIH with 4 3/4" bit. Clean out sand 8900'-9400'.
- 6) Run production equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Hobbs Area Superintendent DATE August 18, 1987

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE Aug 25 1987

CONDITIONS OF APPROVAL, IF ANY: