

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002529829
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	VIERSEN
8. Well No.	3
9. Pool name or Wildcat	Shipp Strawn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Pennzoil Exploration and Prod. Co.	
3. Address of Operator P.O. Drawer 1828 - Midland, TX 79702-1828	
4. Well Location Unit Letter 0 : 150 Feet From The South Line and 2080 Feet From The East Line Section 4 Township 17-S Range 37-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3774.6 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P&A well per the attached well bore diagram.

- 1) Set CIBP w/35' cmt @ 11,000'
- 2) Load hole w/10#/gal brine mud
- 3) Cut & pull 5 1/2" casing @ $\pm 8500'$
- 4) Set 100' (50 sk) stub plug 50' in & out of stub-tag
- 5) Set balanced plugs as follows:
6250-6350' - 50 sks
4239-4139' - 50 sks; 50' in & out of 8 5/8" shoe - tag
2031-1931' - 35 sks
- 6) Perforate 8 5/8" casing @ 455' and circulate cmt to surface using 400 sks.
- 7) Install marker & restore location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy M. Hodgins TITLE Engineer DATE 05/04/92
TYPE OR PRINT NAME Randy M. Hodgins TELEPHONE NO. 915/682-7316

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: