

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. NAME OF OPERATOR

Siete Oil & Gas Corporation

2. ADDRESS OF OPERATOR

P. O. Box 2523, Roswell, NM 88201

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1700' FNL & 330' FWL SW/4 NW/4

16. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, GR, etc.)

3708 GR

4. LEASE DESIGNATION AND SERIAL NO.

NM 9016

5. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Inca Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

East Shugart Delaware

11. SEC., T., R., N., OR S.E. AND
SURVEY OR AREA

Section 19: T18S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

14. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) cement production casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/18/87 TD 7 7/8" hole to 5500' @ 1:45 p.m. - RU Schlumberger & ran logs as follows: CNL, LDT, GR, CALIP, DLL, MSFL, EPT & FMS.

6/19/87 RU & ran 133 jts. of 5 1/2" 15.5# J-55 csg. (5528') set @ 5500' KB & cemented first stage w/570 sks. Dowell Std. containing 3# D-44 sk & .5% D-112 - plug down @ 8:00 p.m. circulated 50 sks. to pit - stage tool @ 2966'.

6/20/87 Cemented 2nd stage w/600 sks. DLW III Std. containing 8# D-44 sk & 1/4# D-29/sk. - plug down @ 1:15 a.m. - circulated 35 sks. to the pit.

RECEIVED

JUN 23 11 23 AM '87

CARLSBAD RESOURCE
AREA HEADQUARTERS

ACCEPTED FOR RECORD

SJS

JUN 24 1987

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

H.D. Justice

TITLE Drlg. & Prod. Vice President

DATE 6/22/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

JUN 29 1987

**OCD
HOBBES OFFICE**