

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30022
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B - 1565
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	266
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐ HORIZONTAL ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter H : 1971 Feet From The NORTH Line and 1310 Feet From The EAST Line Section 36 Township 17S Range 34E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4009' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	
OTHER: ☐	

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	
OTHER: ☐	HORIZONTAL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-23-99: TOH W/TBG.NDWH. NUBOP. TIH W/BIT & CSG SCRAPER TO 4150'. LOG CALIPER FR 4610-4300. TIH W/RBP & SET @ 4100'. REL & TEST CFSG TO 1000 PSI.RD SERV UNIT.
 10-28-99: MIRU RIG #119. NUBOP & FLOWLINE.TIH W/DP & RETR HEAD.LATCH ONTO RBP @ 4100'. REL PLUG.RUN GYRO SURVEY.SET WHIPSTOCK.
 10-30-99: CIRC CLN @ 4600'. CIRC DN TO 4700'. SET PLUG @ 4107'.NDBOP. NUMANUAL BOP.
 11-11-99: REL RBP. RE SET RBP @ 4107'. RU WL & SET PLUG. TIH W/WL & SET RETR PLUG @ 4247'. DUMP 3" SAND ON TOP OF PLUG. TIH W/BIT & DP. TIH W/WHIPSTOCK TO SAND/RBP @ 4245'.
 11-12-99: MILL 4227-4232,4236,4240,4249,4281,4313,4439,4471,4491,4534,4652,4661,4753,4765,4817,4841,4879,4942,4958,4978,5020,5069,5191, SLIDE DRILL 5101-5147,5164,5179,5196,5216,5259.
 11-16-99: SLIDE DRILL 5259-5278,5322,5354,5417,5427,5575,5822. TD HLE 11-16-99.
 11-17-99: RUN TDT LOG FR 5622 TO WINDOW.TIH W/RBP & SET @ 4107'. TEST TO 800 PSI. NDBOP. NU RENTAL BOP. REL RIG 11-17-99
 11-21-99: MIRUSU. NUBOP. PU RETR TOOL & TIH TO TOP 4016'.
 11-22-99: LATCH RBP @ 4107'. REL. TIH W/BENT SUB, PKR, TBG. NU TREE. TEST ANNULUS TO 1000 PSI. RD SERV UNIT.
 11-25-99: ACIDIZE GRAYBURG/SAN ANDRES FORM W/35,000 GALS 20% HCL & 25,K900 GALS WF130 PAD. FLOW TEST WELL.
 11-30-99: MIRU SERV UNIT. CIRC BRINE DN TBG. ND FRAC TREE.
 12-01-99: PUMP 50 BBLS BRINE DN TBG. WENT IN WINDOW W/RETR HEAD. WRK DN TO RBP. TAG UP ON SAND. CIRC 180 BBLS WTR ON TOP OF PLUG. LATCH ONTO PLUG & REL. TIH W/TBG FOR KILL STRING @ 4136'. NU HYDRIL.
 12-02-99: RAN PROD EQPT: MOTOR, GAS SEPR, PUMP, TBG. START PUMPING.
 12-05-99: ON 24 HR OPT. PUMPED 258 BO, 1124 BW, & 368 MCF. OPEN HOLE 4234-5622 SAN ANDRES.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 12/14/99

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: _____ TITLE _____

DATE _____