

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED  
JUN 13 3 03 PM '95  
N.M. OIL CONS. COMMISSION  
FORM APPROVED 88740  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS  
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Harvey E. Yates Company

3. Address and Telephone No.

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

E, 1650' FNL & 990' FWL  
SEC. 12, T-18S, R-32E

5. Lease Designation and Serial No.

NM-40456

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

CHEVRON 12 FEDERAL # 2

9. API Well No.

30-025-30028

10. Field and Pool, or Exploratory Area

YOUNG BONE SPRING, N.

11. County or Parish, State

LEA CO., NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment

☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other P&A

TYPE OF ACTION

☐ Change in Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5-30-95 SET CIBP 6720'. CIRC HOLE w/ 10# BRINE GEL. CAP CIBP w/ 50' CMT ON TOP.  
5-31-95 CUT 5 1/2" CASING @ 2978' & POOH LAYING DOWN.  
PUMP 50 SKS PLUG @ 3028', (50' INSIDE STUB). SI WOC.  
6-1-95 TAG CMT @ 2872' (157' PLUG). PULL TO 450' AND PUMP 40 SK PLUG.  
PULL TO 50' AND PUMP 20 SK PLUG TO SURFACE. CUT OFF WELL HEAD EQUIPMENT.  
INSTALL DRY HOLE MARKER. BACKFILL WORK PIT. P&A COMPLETE.

LOCATION TO BE CLEANED AND REHABED AFTER PARTNER APPROVAL ON MATERIAL DISTRIBUTION.

Approved as to Payment of Well Core  
Liability under bond is retained until  
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

*[Signature]*

RAY F. NOKES

Title

PROD. MGR./ ENG.

Date 6/9/95

(This space for Federal or State office use)

Approved by

(ORIG. SGD.) JOE G. LARA

Title

PETROLEUM ENGINEER

Date 7/13/95

Conditions of approval, if any:

RECEIVED

JUL 17 1995  
LCD HOBBS  
OFFICE