

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instruction
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Harvey E. Yates Company	8. FARM OR LEASE NAME Chevron 12 Federal
3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88201	9. WELL NO. #2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below) At surface 990' FWL & 1650' FNL	10. FIELD AND POOL, OR WILDCAT North Young - <i>Ben</i>
14. PERMIT NO. 30-025-30028	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12, T18S, R32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3874.0 GL	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETION	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)	Completion		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and acres pertinent to this work.)*

10/4/87 Perf 9480-90 (2spf) Swab test.
10/8/87 Set CIBP @ 9475. Perf 9457-65 (2spf) Swab test.
10/11/87 Set retainer @ 9400 & squeeze w/45 sks. Drill out cement & retainer to 9473.
10/14/87 Abra-jet perfs @ 9458 & acidize w/1000 gals 15% HCL. Swab test.
10/17/87 Set CIBP @ 9440. Perf 8578-92 & acidize w/100 gals 20%. Swab test.
10/22/87 Set CIBP @ 8570. Perf 8434-8514 (2spf). Acidize w/500 gals 20%. Swab test.
10/24/87 Acidize w/5000 gals 20% & balls. Swab test.
10/27/87 Acidize w/10,000 gals 28% & N2. Swab test.
11/3/87 Acidize w/5000 gals 28% & balls. Swab test
11/10/87 Run rods & pump.

RECEIVED

NOV 20 1987

SJS

RECEIVED
NOV 10 1987

18. I hereby certify that the foregoing is true and correct

SIGNED A. M. Young NM Young TITLE Drilling Superintendent DATE 11/18/87

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side