

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-30102

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-2076

7. Lease Name or Unit Agreement Name

Central Unit Vacuum

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐ Injector

2. Name of Operator

Texaco Exploration & Production, Inc.

8. Well No.

223

3. Address of Operator

P. O. Box 3109, Midland, TX 79702

9. Pool name or Wildcat

Vacuum Grayburg SA

4. Well Location

Unit Letter K : 1821 feet from the South line and 1330 feet from the West line

Section 25

Township 17S Range 34E

NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH w/ws Tag TOC on CIBP @ 4155' (set in 8/21/95) Displace hole w/MLF, 9.5# brine w/25# gel P/BBL.
2. Spot 40 Sx plug 3800'-3600' (Queen)
3. Spot 40 Sx plug 2800'-2600' (B-Salt, Yates)
4. Spot 40 Sx plug 1650'-1450' (13 3/8" shoe, T-Salt) WOC Tag
5. Spot 40 Sx plug 450'-250' (20' Shoe) WOC Tag
6. 10 Sx Surf, 10'-Surf. Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. T. Corbitt

TITLE

FACILITY ENGINEER

DATE *6-7-01*

Type or print name

JAMES T. CORBITT

Telephone No. *915 688-44*

(This space for State use)

APPROVED BY

TITLE

DATE *12 2001*

Conditions of approval, if any: