

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30103
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1565
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	253
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	4018' GL

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	P.O. BOX 730, HOBBS, NM 88240
4. Well Location	Unit Letter <u>C</u> : <u>675</u> Feet From The <u>NORTH</u> Line and <u>1330</u> Feet From The <u>WEST</u> Line Section <u>36</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	4018' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Temporarily Abandon ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/9/96

NOTIFIED NMOCD. TOH W/ RODS & PUMP. INSTALLED BOP. TOH W/ TBG.

2. SET CIBP @ 4230' & CAPPED W/ 36" CMT, PBTD @ 4194'.

3. CIRCULATED HOLE W/ INHIBITED FLUID & TESTED AS PER NMOCD GUIDELINES TO 520# FOR 30 MINUTES, HELD OK. MR. BUDDY HILL OF THE NMOCD WITNESSED TEST.

4. REQUEST TEMPORARY ABANDON WELL STATUS THROUGH 4/9/2001.

(ORIGINAL CHART ATTACHED, COPY OF CHART ON BACK)

(NEW TEPI INTERNAL STATUS: TR-O)

This Approval of Temporary  
Abandonment Expires


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engr Asst DATE 4/16/96  
TYPE OR PRINT NAME Monte C. Duncan Telephone No. 397-0418

(This space for State Use)

APPROVED BY DIS. DIST. SUPERVISOR TITLE DIS. DIST. SUPERVISOR DATE APR 18 1996

CONDITIONS OF APPROVAL, IF ANY:




APR 18 1988

Received  
Hobbs  
APR 18 1988  
PRINTED IN U.S.A.

**TEXACO EXPLORATION AND PRODUCTION INC**

PO BOX 730  
HOBBS NEW MEXICO 88241-0730

Ltr. C, Sec. 36, T-17-S, R-34-E  
Lea, N.M.  
30-025-30103



4/9/96 #253  
CV 26  
SUPERVISOR  
PACKER SETTING DEPTH 4230  
PACKER TYPE  
PERFORATIONS 425-1-472  
CU 4253

0

Finish