

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30110
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1687
7. Lease Name or Unit Agreement Name Marathon State
8. Well No. 1
9. Pool name or Wildcat Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3835.8 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Re-entry</u>
2. Name of Operator Tom Schneider
3. Address of Operator 505 N Big Spring St., Suite 204 Energy Sq. Midland, TX
4. Well Location Unit Letter <u>B</u> : <u>1300</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>27</u> Township <u>17-S</u> Range <u>36-E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3835.8 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/25/90...Laid down rods and pump. Pumped 25 sx. of C cement at 5169 feet. Pulled up and WOC.

6/26/90...Trip into hole with tubing and tagged plug at 4,936. Circulated hole and mixed mud. Pumped 25 sx. of C cement at 4,530. Cut and pulled 2,994 feet of 5 1/2" casing. Trip into hole, circulate and mix mud, pumped 40 sx. of C cement at 3,050 feet. SIFN.

6/27/90...Trip into hole with tubing and tagged plug at 2,945 feet. Pulled to surface and set 10 sx. of C cement at Surface.

Ray Smith with Commission witness all operations. Cementing by Triple "N" Services, Inc. Midland, Texas.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Thomas Schneider TITLE operator representative DATE 7/17/90

TYPE OR PRINT NAME Thomas Schneider TELEPHONE NO. (915) 682-6340

(This space for State Use)

APPROVED BY Lytle E. Tomaroff TITLE OIL & GAS REGULATOR DATE FEB 01 1991

CONDITIONS OF APPROVAL, IF ANY:

1
JUL 1 8 1990

JUL 1 8 1990

WORLDWIDE
BOOKS OFFICE