Form 3160-3 (November 1983) (formerly 9-331C)

SUBMIT IN TRIPL (Other instructions on reverse side) 5 - 625 36/11

5. LEASE DESIGNATION AND SERIAL NO.

UNITED STATES DEPARTMENT OF THE INTERIOR

roim approved,	
Budget Bureau No.	1004-0136
Expires August 31,	1985

BUREAU OF LAND MANAGEMENT					NM 9019				
APPLICATION	N FOR PERMIT	TO DRILL,	DEEPEN	OR PLUG E	ACK	6. IF INDIAN, AL	LOTTED O	R TRIBE NAME	
DRILL XX DEEPEN DEEPEN PLUG BACK						7. UNIT AGREDMENT NAME			
OIL G	AS		SINGL		'LE	8. FARM OR LEA	SE NAME		
WELL XX WELL OTHER ZONE ZONE NAME OF OPERATOR					Mohawk Federal				
Siata Oil &	Gas Corporation	n				9. WELL NO.			
ADDRESS OF OPERATOR						1			
P. O. Box 2523 Roswell, New Mexico 88201						10. PIELD AND POOL, OR WILDCAT East Shugart Delaware 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Sec. 19: T18S, R32E			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*) At surface 1650' FWL & 2310' FSL NE/4 SW/4 Unit Letter K At proposed prod. zone									
					DISTANCE IN MILES				AND DIRECTION FROM NE
						Eea		NM	
15 miles SE	OSED*	· · · · · · · · · · · · · · · · · · ·	16. No. 01	ACRES IN LEASE		OF ACRES ASSIGNED	<u> </u>		
LOCATION TO NEAREST PROPERTY OR LEASE LINE, FT.		330'		680	10 1	THIS WELL 40			
(Also to nearest drig, unit line, if any) 18. DISTANCE FROM PROPOSED LOCATION*			19. Ркоро	SED DEPTH	20. ROTA	CARY OR CABLE TOOLS			
TO NEAREST WELL, I OR APPLIED FOR, ON TE	DRILLING, COMPLETED,			5500 '	Ro	Rotary			
. ELEVATIONS (Show wi	hether DF, RT, GR, etc.)		·			22. APPROX. DA	ATE WOR	K WILL START	
						11/1,	/87		
J		PROPOSED CASI	NG AND C	EMENTING PROGR	AM				
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER	FOOT	SETTING DEPTH		QUANTITY OF CEMENT			
12 ½	8 5/8	24#		350'		230 sks.	CH	CULATE	
7 7/8	5½	15.5#		5500'		1200 sk			
Selectiv Attachme	vely Perforate	& Treat Pay	Zone.			5 (1)	-:::	IVED	
Sug	rvey Plat (C-10 oplemental Dril rface Use Plan					· ·		-	
one. If proposal is to reventer program, if a 4.	Justin	onally, give pertine	nt data on s	back, give data on ubsurface locations a	and measur	ed and true vertice	al depth	new product . Give blow	
one. If proposal is to reventer program, if a 4.	drill or deepen directiony.	onally, give pertine	nt data on s	ubsurface locations a	and measur	ed and true vertice	al depth	. Give blow	
one. If proposal is to reventer program, if a 4.	drill or deepen directiony.	onally, give pertine	V.P	ubsurface locations a	and measur	ed and true vertice	al depth	. Give blow	
signed (This space for Fed	o drill or deepen directiony.	onally, give pertine	V.P	. Drilling &	and measur	ed and true vertice	ctobe	r 14, 19	

RECEIVED 1987