

Form 3160-5
November 1983)
Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. NAME OF OPERATOR Harvey E. Yates Company		3. LEASE DESIGNATION AND SERIAL NO. NM 55145	
2. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88202		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter D, 330' FNL & 990' FWL		7. UNIT AGREEMENT NAME	
14. PERMIT NO. 30-025-30266		8. FARM OR LEASE NAME Querecho Plains 22 Federal	
15. ELEVATIONS (Show whether OF, RT, OR, etc.) 3781.8 GL		9. WELL NO. 1	
		10. FIELD AND POOL, OR WILDCAT Young Bone Spring	
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 22 T18S, R32E	
		12. COUNTY OR PARISH Lea	
		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRAC TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

WATER SHUT-OFF

FRAC TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-3-88 Acdz w/2000 gals 7 1/2" MSR 100 across perfs @ 7008-7042 (OA)
9-3-88 Frac perfs 7008-42 w/29,000 gals 70Q Fnam w/50,000# 16-30 Ottawa
9-9-88 Put well on pump w/SN @ 7501 & anchor @ 6910'. Turn over to pumper.

NOTE: Correction on footages on SN & anchor

ACCEPTED FOR RECORD

NOV 11 1988

CARLSBAD, NEW MEXICO

RECEIVED
NOV 4 11 04 AM '88
OAS
AREA

I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Manager/Engineer

DATE

Oct. 31, 1988

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

NOV 28 1986

CCO

HOBBS OFFICE