

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation. Use "APPLICATION FOR PERMIT" for such proposals.)

1. IF APPLICABLE, ATTACHED TO FORM 9019

2. SURF ELEVATION DATA

3. DATA ON LEADS HAND

Lakota Federal

4. WELL NO.

1

5. TOWN AND RANGE OR WILDCAT

Young North (Bone Spring)

6. SEC. T. R. OR BLM. AND COUNTY OR ADJ.

Sec. 17: T18S, R32E

7. COUNTY OR PARISH

Lea

8. STATE

NM

9. PERMIT NO.
30-025-30313

10. ELEVATIONS (Show whether on, at, or off)
3780' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TEST

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Amend TD

PULL OR ALTER CASING

MULTIPLE COMPLETS

ABANDON

CHANGE PLANE

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

11. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/17/88 Amend TD from 9200' to 9300'.

RECEIVED
JUN 20 8 20 AM '88

RECEIVED

12. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production/Reservoir Engineer

DATE 6/17/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

JUL 26 1988

Carl M. Chester
CARLSBAD, NEW MEXICO

*See Instructions on Reverse Side