

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO. 30-035-30372
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-654
7. Lease Name or Unit Agreement Name State "2"
8. Well No. 1
9. Pool name or Wildcat Shipp Strawn

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Amerind Oil Company Limited Partnership	
3. Address of Operator 415 W. Wall Suite 500, Midland, TX 79701	
4. Well Location Unit Letter <u>F</u> : <u>2020</u> Feet From The <u>North</u> Line and <u>2130</u> Feet From The <u>West</u> Line Section <u>2</u> Township <u>17S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3756' GL 3772' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/5/90 MI Plugging equipment.  
2/6/90 POOH w/372 jts 2-7/8" N-80 tbg, set & tagged CIBP @ 11,550' w/10 sx CIs "H".  
2/9/90 Cut 5-1/2" csg @ 9300'. 2/10/90 Pulled 150 jts csg.  
2/12/90 Finished POOH w/5-1/2" csg (221 jts total). TIH w/2-7/8" tbg to 9363'. Spotted 35 s CIs "H" plug (tagged). Pulled 25 stands.  
2/13/90 TIH & tagged TOC @ 9246'. Plugged well as follows:  
Plug 1 CIBP 11,550 w/10 sx CIs "H"  
Plug 2 35 sx CIs H 9,366 -9,246 (120') tagged  
Plug 3 30 sx CIs H 8,708 -8,606 (103')  
Plug 4 30 sx CIs H 6,610 -6,506 (104')  
Plug 5 35 sx CIs H 4,542 -4,430 (112') tagged  
Plug 6 30 sx CIs H 2,078 -1,973 (105')  
Plug 7 10 sx CIs H 30 -surface (30')

Set dry hole marker, rel plugging equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert C. Leibrock TITLE Partner DATE 3/5/90  
TYPE OR PRINT NAME Robert C. Leibrock TELEPHONE NO. 915/682-8217

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JUL 19 1990

CONDITIONS OF APPROVAL, IF ANY: