

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-30386
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Voyager-Shipp 10
Well No 1Y
Pool name or Wildcat Humble City, Strawn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
Name of Operator Nearburg Producing Company	Well No 1Y
Address of Operator 3300 N A St., Bldg 2, Suite 120, Midland, TX 79705	Pool name or Wildcat Humble City, Strawn
Well Location Unit Letter <u>M</u> : <u>990</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>10</u> Township <u>17S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3762 GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Plug and Abandon ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Started drilling cmt plugs 1/13/03. Set cmt plug @ 7515'. Directionally drld to 11,780'. Logged well.

Plug and abandon well as follows (plugs verbally approved by Gary Wink w/ OCD):

Plug #1 ☐ 11,775' - 11,675'. 30 sxs class H + additives ☐
Plug #2 ☐ 11,300' - 11,200'. 30 sxs class H + additives ☐
Plug #3 ☐ 9600' - 9500'. 30 sxs class H + additives ☐
Plug #4 ☐ 7600' - 7500'. 30 sxs class H neat. ☐
Plug #5 ☐ 5600' - 5500'. 30 sxs class H neat. ☐
Plug #6 ☐ 4250' - 4100'. Tagged @ 4100'. 50 sxs class H neat w/ 1% KCL. ☐
Plug #7 ☐ 2200' - 2100'. 30 sxs class H neat. ☐
Plug #8 ☐ 500' - 400'. 30 sxs class H neat. ☐
Plug #9 ☐ 10 sxs class H neat surface plug. ☐
ND BOPE, clean pit and release rig @ 0230, 2/9/03. ☐

Logs included.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. R. Willis TITLE Drilling Supt DATE 02-19-2003

TYPE OR PRINT NAME H. R. Willis

TELEPHONE NO. 915/686-8235 ext 223

(This space for State Use)

ORIGINAL SIGNED BY

GARY W. WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

DATE

MAR 31 2003