

Form 3160-5
November 1983)
Formerly 9-331)

N. M. OIL CONS. COMMISSION
P. O. BOX 1000
HOBBS, NEW MEXICO 88240
UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. NM-56263
2. NAME OF OPERATOR Manzano Oil Corporation	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 2107, Roswell, NM 88202-2107	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FSL & 1650' FEL	8. FARM OR LEASE NAME Sun Pearl Federal
14. PERMIT NO. 30-025-30409	9. WELL NO. #1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3700.4 GL	10. FIELD AND POOL, OR WILDCAT Pearl Queen
	11. SEC., T., R., N., OR BLK. AND SUBST OR AREA Sec 28, T19S, R34E
	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

☐
☐
☐
☐
☐

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

☐
☐
☐
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

☒
☒
☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

☐
☐
☐
☒
☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 8/2/89 Perforate 4781'-4799' (9 holes) and 4839' - 4447' (6 holes). Set RBP @ 4910'. Pull packer to 4847'. Spot 1 bbl acid across perfs. Pull & set packer @ 4822'. Acidized with 750 gal 15% NEFE & 12 ball sealers. Total load 45 bbl.
- 8/3/89 Pull plug to 4827' & set. Spot 1 bbl acid across perfs. Pull packer to 4728' & set. Acidized with 1000 gal 15% NEFE & 18 ball sealers. Total load 48 bbl.
- 8/4/89 Unset packer & RBP. Set RBP @ 4940'. Frac down 4-1/2" casing with 30K gal 40# cross link gel plus 46K# 20/40 sand & 16K# 12/20 sand. Total load 870 bbl.

RECEIVED
AUG 18 11 40 AM '89
BUREAU OF LAND MGMT.
HOBBS, NM.

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED Alison Wiggins

TITLE Land/Drilling Secretary

DATE 8/15/89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

ACCEPTED FOR RECORD

AUG 23 1989

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

RECEIVED

AUG 28 1989

OCD
HOBBS OFFICE