

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30592
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. —
7. Lease Name or Unit Agreement Name F. M. Holloway
8. Well No. 1
9. Pool name or Wildcat South Knowles - Dev.
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3682.2 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Page Energy
3. Address of Operator 1110 N. Big Spring, Midland, TX 79701	4. Well Location Unit Letter J : 2086 Feet From The South Line and 1980 Feet From The East Line Section 13 Township 17S Range 38-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3682.2 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Complete Well <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-10-89 MI Completion Unit. Drill out DV Tool @ 7079'. Test to 1500 PSI. OK

6-11-89 Drill FC & FS

6-13-89 Drill formation below 5 1/2" casing @ 12,052. TD 12,072.

6-25-89 Acidize well w/500 gals 15% NEFE

6-26-89 SWB well to 3,500' FS. Well started Flowing

6-27-89 Ran potential test. Well flowed 269.5 BO-No water-175,000 CF Gas in 24 hrs. FTP 60 PSI

6-28-89 SI well to build tank battery.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE O. H. Routh TITLE Agent DATE 7-3-89

TYPE OR PRINT NAME O. H. Routh TELEPHONE NO. 915-687-0323

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY:

JUL 10 1989

82-10-116

RECEIVED

JUL 10 1989

OCD
HOBBS OFFICE