RUPE	UNITED STATES TMEN OF THE INTERIC EAU OF LAND MANAGEMENT	The state of the s	Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM - 56749
SUNDRY NC (Do not use this form for pro Use "APPL"	OTICES AND REPORTS: Opposals to drill or to deepen or plug batication FOR PERMIT—" for such pro-	ck to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL V GAS	inn		7. UNIT AGREEMENT NAME
WELL WELL OTHER 2. NAME OF OPERATOR			S. FARM OR LEASE NAME
Texaco Producing, Inc.			Federal (USA) "L"
3. ADDRESS OF OPERATOR			9. WELL RO.
P.O.Box 728, Hobbs, N.M. 88240			2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT Tonto Seven Rivers
Unit Letter F, 23	310' FNL, 2210' FWL		11. SBC., T., E., M., OR BLE. AND SURVEY OR ARMA
14. PERMIT NO.	15. BLEVATIONS (Show whether DF,	PT OP etc.	Sec. 14, T 19S, R33E
12. Parati No.	3679 GR (KB 1	-	Lea NM
16. Charle			
NOTICE OF INT	Appropriate Box To Indicate Notes		THE DOTO
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTUBE TREATMENT X	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON®	SECOTING OR ACIDIZING X	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		Completion or Recomple	of multiple completion on Well tion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED C proposed work. If well is direct nent to this work.) *	DERATIONS (Clearly state all pertinent ctionally drilled, give subsurface locationally drilled, give subsurface locations)	details, and give pertinent dates, ons and measured and true vertical	including estimated date of starting any depths for all markers and zones perti-
1. MIRU pulling	unit on 8-1-89. Ins	stall BOP.	
2. GIH with bit	and tag cement at 3	3627' (FC at 3783'), Drill cement from
3627-3783'. T	Test casing to 1500	psi. Tested from	12:00 noon - 12:30pm
on 8/2/89. Te			5.601
3. Spot 150 gall	lons of 10% acetic a	101d from 3/10 = 3	560'.
4. Perf Seven Rivers intervals 3679 - 3688 & 3697			3/10 at 1 SPF
(24 holes). 5. Acidize perfs with 2000 gallons 15% NEFE HCL and 36 RC			36 RCN ball sealers.
	at perfs with 38000		
sand. Shut in.		-	
7. Clean out sar	nd to 3778'.		
8. GIH with prod	duction equipment.		
	otential ending 9:00) AM on 8/13/89. P	umped 120 BO and
5 BLW. GOR-46	57. GRAV 38.5.		
18. I hereby certify that the foregoing			
SIGNED Colonial Med	zd//S/ TITLE AT	ea Manager	DATE 8-14-89
(This space for Federal or State o	ffice use)		
APPROVED BY (OPIO SOD.)	· ·		
CONDITIONS OF APPROVAL IF			DATE