Submit 3 Copies

State of New Mexico to Appropriate District Office Energy, Minerals and Natural Resources Department Form C-103 Revised 1-1-89 DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 <u>30-025-30669</u> DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410 5. Indicate Type of Lease STATE FEE XXX 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: MET X WELL OTHER 2. Name of Operator Price Family 1L Nearburg Producing Company 8. Well No. Address of Operator 419 W. Cain Hobbs NM 88240 9. Pool name or Wildcat 4. Well Location Shipp - Strawn : 2,130 Feet From The Unit Letter South 660 Line and Feet From The 1 Line Section T-17-S Township thip Range 3/-E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Lea, NM County 3,732.9' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT XXX PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed Set 5½ CIBP @ 10500' cap W35' cmt 1) 2) Load hole with mud Cut 5½ csg @ 6460' Pulled out of hole 3) Spot 25 sx cmt Plug @ 5½ stub 6514' W.O.C., plug was not there, respot 50 sx cmt 4) Plug @ 6514' W.O.C. Tagged cement plug @ 6492' Plug was not high enough respot W/50 sx cmt W.O.C. @ 6492' Tagged plug @ 6460' Respot W/50 sx cmt. W.O.C. Tagged cmt top Spot 50 sx cement plug @ 4757' W.O.C. Tagged cemet top @ 4655' 5) Spot 35 sx cement plug @ 2100' 6) Spot 35 sx cement plug @ 521' 7) Spot 10 sx cement Surface plug Set PA marker Job completed 11-12-96 I hereby curally that the information above is true and complete to the best of my knowledge and belief. SIGNATURE . TYPE OR PRINT NAME TELEPHONE NO