

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30715
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	744880
7. Lease Name or Unit Agreement Name	STATE "BA"
8. Well No.	11
9. Pool name or Wildcat	VACUUM GLORIETA + VACUUM BLINERY

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator	TEXACO PRODUCING INC.
3. Address of Operator	P.O. Box 3109, MIDLAND, TEXAS 79702
4. Well Location	Unit Letter <u>D</u> : <u>989</u> Feet From The <u>WEST</u> Line and <u>660</u> Feet From The <u>NORTH</u> Line
Section <u>36</u> Township <u>17 SOUTH</u> Range <u>34 EAST</u> NMPM <u>LEA</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>GR-4006'</u> <u>RB-4018'</u> <u>KB-4019'</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) 12-27-89 SET CIBP @ 6250' TEST TO 3000# 9:00 AM to 9:30 AM (30 min) Dump 20' CMT ON TOP PBTB - 6230'.
- 2) PERF 6101' - 6146' - 90 HOLES 2 JSFP
- 3) ACIDIZE WITH 5000 GAL 15% NEFE W/150 BALLS
- 4) SWAB 15 BNO + 55 BLW IN 13 HOURS
- 5) PUT ON PUMP + TEST 12-30-89
- 6) SET RBP @ 6050 TEST WITH 3000 psi 1-8-90
- 7) PREP TO PERF
- 8) WEDGE WIRELINE PERF 2 JSFP 5967' - 5993' 54 HOLES
- 9) PREP TO ACIDIZE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C.P. Basham TITLE Drilling Superintendent DATE 1-9-90
TYPE OR PRINT NAME C.P. BASHAM (915)
TELEPHONE NO. 688-4625

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 16 1990

CONDITIONS OF APPROVAL, IF ANY: