

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL  
(Other instructions  
verse side)

E\*  
re-

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO  
NM-0381550 (C)  
6 IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. NAME OF OPERATOR  
Harvey E. Yates Company  
3. ADDRESS OF OPERATOR  
P.O. Box 1933, Roswell, New Mexico 88202  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface 1650' FSL & 2310' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Mobil 24 Federal

9. WELL NO.  
#1

10. FIELD AND POOL, OR WILDCAT  
Lea Bone Springs

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 24, T19S, R34E

14. PERMIT NO.  
30-025-30839

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3798.6 GL

12. COUNTY OR PARISH  
Lea  
13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8/8/90 Abraza jet cut 2 holes at 10,241', Acdz w/500 gals 15% NEFE +  
750 gals 20% NEFE  
9/1/90 Abraza jet cut 2 holes each at 9755' and 9751', Acdz w/1500  
gals 15% NEFE  
9/9/90 Run tbg, anchor @ 9716' and SN @ 10,488'  
Return all zones to production

18. I hereby certify that the foregoing is true and correct

SIGNED T. Gum T. Gum TITLE Engineer

DATE 9/11/90

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side