Form 3160-5 (November 1983) (Formerly 9-331) UNITED STA DEPARTMEN. OF THE BUREAU OF LAND M	HE INTERIOR (Other Instructions returns side)	5. LEASE DESIGNATION AND SERIAL NO
SUNDRY NOTICES AND F (Do not use this form for proposals to drill or to c Use "APPLICATION FOR PERMI	REPORTS ON WELLS deepen or plug back to a different reservoir. IT for such proposals.)	G IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS OTHER 2. NAME OF OPERATOR	JAN 15 II 3 AM 181	7. UNIT AGREEMENT NAME Young Deep Unit 8. FARM OR LEASE NAME
Harvey E. Yates Company 3 ADDRESS OF OPERATOR P.O. Box 1933, Roswell, N.M. 4 Location of Well (Report location clearly and in accordant surface) At surface 1650' FSL & 33	dance with any State requirements.	9. WELL NO. #12 10. FIELD AND POOL, OR WILDCAT North Young Bone Spring 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO 15 ELEVATIONS (S	Show whether DF, RT, GR, etc.) 3863.5 GL	Sec. 4, T18S, RAGE 12. COUNTY OR PARISH 13. STATE Lea NM
TEST WATER SHUT-OFF PULL OR ALTER CASE FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* CHANGE PLANS (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATION: (Clearly St proposed work. If well is directionally drilled, give nent to this work.)* 1) Set RBP @ 8395' 2) Perf 8228-8318' (oa) 3) Acdz w/2500 gals 20% NEFE 4) Pkr set @ 8103' 5) Kick well off flowing	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Perf & ac (Note: Report result Completion or Recommendate and present dates subsurface locations and measured and true vertices.	REPAIRING WELL ALTERING CASING ABANDONMENT* IC 8 of multiple completion on Well
18. I hereby certify that the foregoing is true and correct	Λ.σ	
SIGNED Signed Fine Gum (This space for Federal or State office use)	TITLE Engineer	DATE 1/15/91
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE

*See Instructions on Reverse Side