

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO

LC 064638

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Young Deep Unit

8. FARM OR LEASE NAME

9. WELL NO.

12

10. FIELD AND POOL, OR WILDCAT

North Young Bone Springs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 4, T18S, R32E

12. COUNTY OR PARISH

LEA

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P. O. Box 1933 Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1650' FSL & 330' FEL

14. PERMIT NO.

30-025-30866

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3863.5 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Test & Completion

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5/17/90 Drill out DV Tool @ 7424' & clean out to bottom

5/19/90 Perforate 8780' & 8455 w/ 2 shots each

5/20/90 Squeeze 8780' w/1000 sks 'H', Squeeze 8455' w/1000 sks 'H'

5/22/90 Drill out Squeezes to 8770'

5/24/90 Perforate 8470-8764' w/ 2 shots each, Acidize w/4300 Gal mud, acid & Ballsealers Swab Test

5/27/90 Frac w/245,000 gal BS 50 (3-1) & 335,000 lbs 16/20 LWD

5/31/90 Put on Production

18. I hereby certify that the foregoing is true and correct

SIGNED

N.M. Young

TITLE Drilling Superintendent

DATE 6/7/90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side