

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 56263
2. NAME OF OPERATOR MANZANO OIL CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 2107, Roswell, NM 88202-2107		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FNL & 1940' FEL		8. FARM OR LEASE NAME SUN PEARL FEDERAL
14. PERMIT NO. API 30-025-30892		9. WELL NO. #3
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3707.1'		10. FIELD AND POOL, OR WILDCAT Pearl Queen
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 28-T19S-R34E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-12-90: Perforate Penrose Zone 4933-39'; 4837-44'; 4787-95'.
6-13-90: Acidize perms 4933-39' w/750 gallons 15% NE/FE acid.
6-14-90: Acidize perms 4837-44' w/800 gallons 15% NE/FE acid.
Acidize perms 4787-95' w/800 gallons 15% NE/FE acid.
6-16-90: Frac perms 4933-39' w/14,500 gallons 40# gel + 34,000 lbs sand. Frac 4787-95' and 4837-44' w/35,000 gallons 40# gel + 73,500 lbs sand.
6-19-90: RIH w/1 jt mud anchor and 152 jts 2-3/8" J55 EUE tubing, set mud anchor @ 4971' and tbg @ 4938'. Released unit and prep to set pump.

ACCEPTED FOR RECORD

Adm

JUL 17 1990

CARLSBAD, NEW MEXICO

RECEIVED
JUL 12 10 59 AM '90
CAREY
AREA ENGINEERS

18. I hereby certify that the foregoing is true and correct

SIGNED *Sher Williams*
Sher Williams

TITLE Production Clerk

DATE July 11, 1990

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED

JUL 18 1960

CC

MOBILE