

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30971
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 744880
7. Lease Name or Unit Agreement Name STATE -BA-
8. Well No. 13
9. Pool name or Wildcat VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-4003', KB-4016'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
TEXACO PRODUCING INC.

3. Address of Operator  
P. O. Box 3109 Midland, Texas 79702

4. Well Location  
Unit Letter C : 990 Feet From The NORTH Line and 1880 Feet From The WEST Line  
Section 36 Township 17-SOUTH Range 34-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
GR-4003', KB-4016'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: COMPLETING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU X-PERT UNIT. CLEAN OUT TO PBTD OF 6220'. TESTED CASING TO 3000# FOR 30 MINUTES 11-18-90.
2. PENWOOD RAN GR-CCL FROM 6220' TO 5585'. PERF WITH 2 JSPF: 6124-29, 6137-43, 6146-58, 6162-67. 56 HOLES. WESTERN ACIDIZED WITH 4200 GAL 15% NEFE. 11-19-90. SWAB 2 BNO & 19 BLW IN 6 HOURS.
3. TIH & SET RBP @ 6115'. TEST TO 3000#. PERF WITH 2 JSPF: 6065-74, 6095-6100. 28 HOLES. WESTERN ACIDIZED WITH 1000 GAL 15% NEFE. 12-3-90. SWAB 10 HOURS 12-4-90. RECOVERED 53 BLW.
4. TOH WITH RBP. TIH WITH 2 7/8 TUBING, PUMP & RODS. PUMP 24 HOURS 12-18-90. RECOVERED 2 BNO & 51 BFW.
5. HALLIBURTON ACIDIZED WITH 2100 GAL 15% NEFE. 12-20-90. TIH WITH TUBING, PUMP & RODS.
6. PUMP 24 HOURS 12-24-90. RECOVERED 33 BLW.
7. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C.P. Basham / cwh TITLE DRILLING SUPERINTENDENT DATE 12-27-90  
TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

DEC 31 1990