

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. LC-064638
2. Name of Operator Harvey E. Yates Company	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Box 1933 Roswell, NM 88202	7. If Unit or CA, Agreement Designation 8910180420 Young Deep Unit #27
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit J: 1650' FSL & 1650' FEL Section 04, T-18S, R-32E	8. Well Name and No. #27
	9. API Well No. 30-025-30976
	10. Field and Pool, or Exploratory Area Undesignated
	11. County or Parish, State Lea County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other _____	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/14/93 Spot 30 sxs cement @ 2805' - 2505' - tagged.
12/14/93 Spot 35 sxs cement @ 1675' - 1489' - tagged - pulled 1625' og 5½".
12/15/93 Spot 35 sxs cement @ 1315' - 1215'.
12/15/93 Spot 10 sxs cement @ 30' - surface.

Install dry hole marker
Circulate with mud.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed Joe G. Lara Title Engineer Date 1-7-94

(This space for Federal or State office use)

Approved by **(ORIG. SGD.) JOE G. LARA**

Title **Petroleum Engineer**

Date 1/28/94

Conditions of approval, if any: