KE ENED Fo (Ju

N.M. OIL CON., COM	MOISSIN
P.O. BOX 1980	
HOBBS, NEW MEXICO	88240
	B

UNITED STATES HOBBS, NEW MEXICO 88240 FORM APPRO DEPARTMENT OF THE INTERIOR Expires: March 3 DEPARTMENT OF THE INTERIOR	
DEPARTMENT OF THE INTERIOR Furinger Month 3	
	ine 1990)
BUREAU OF LAND MANAGEMENT 5. Lease Designation and S	DUG LL

reau No. 1004-0135 : March 31, 1993

5. Lease Designation and Serial No.
NM-40452
6. If Indian, Allottee or Tribe Name

<u>. (5) </u>	SUNDRY NOTICES AND REPORTS ON WELLS
Do not use	this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.
	Use "APPLICATION FOR PERMIT—" for such proposals

Use "APPLICATION FOR PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Type of Well Oil Well Well Well Other Dry Hole	8. Weli Name and No.
Santa Fe Energy Operating Partners, L.P.	West Shinnery 15 Fed #1 9. API Well No.
3. Address and Telephone No. 550 W. Texas, Suite 1330, Midland, Texas 79701	30-025-31094 10. Field and Pool, or Exploratory Area
(D), 990' FNL and 330' FWL, Sec. 15, T-18S, R-32E	11. County or Parish-State Lea Co. NM

			Lea Co., NM
2.	CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF	ACTION
	Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is planned to plug and abandon the subject well as follows:

- Set CIBP @ 4700' and cap with 50' of cement.
- Cut off 5-1/2" casing 100' above the TOC (approx 2500') and pull 5-1/2".
- Spot 120' plug (C1 "C") at 2560'.
- Spot 100' plug (C1 "C") at 459'.
- 5. Spot 50' plug (C1 "C") at 50'.
- Install dry hole marker.
- 7. Clean location and re-seed as required.

This work will begin on or near September 20, 1994.

Signed Signed CT Federal or State office use)	Sr. Production Clerk	Date	Aug. 19, 1994
(ORIG. SGD.) JOE G. LARA	DETDOLEUM ENGINEER	Date _	9/15/94
Conditions of approval, if any: See attached.			
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly or representations as to any matter within its jurisdiction.	and willfully to make to any department or agency of the United Sta	ites any false.	fictitious or fraudulent statement

or representations as to any matter within its jurisdiction. *See instruction on Reverse Side

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Permanent Abandonment of Wells on Federal Lands

Conditions of Approval

- 1. <u>Approval:</u> Plugging operations shall commence within 90 days from the approval date of plugging procedure.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505)887-6544; for wells in Lea County call (505) 393-3612.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show <u>date</u> well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.