

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-31169

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.
E-6005

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

7. Lease Name or Unit Agreement Name

Texas State

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

2. Name of Operator

Xeric Oil & Gas Company

8. Well No.

1

3. Address of Operator

P.O. Box 51311, Midland, TX 79710

9. Pool name or Wildcat

Pearl (Queen) Sk, South

4. Well Location

Unit Letter G : 2310 Feet From The North Line and 1650 Feet From The East Line

Section 36 Township 19-S Range 3-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3705.2 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well has 8 5/8" Surface Casing set at 445' cemented to surface and 5 1/2" casing set at 5018'. Cemented to surface. Plugging is anticipated to begin immediately upon approval of procedure.

1. Move in and rig-in pulling unit. Pull 2 3/8 tubing out of hole.
2. Tag CIBP @ 4860' @ Cap w/35 sx cement. (top of Penrose)
3. Set CIPB at approx 3850' (top of Seven Rivers). Cap w/35 sx cement.
4. Set 15 sx cement plug at surface.
5. Install dry hole marker.

20 SX PLUG @ 1800

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

Operations Manager

DATE 9/19/91

TYPE OR PRINT NAME

Gary S. Barker

915-683-3171

TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

SEP 23 1991

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

RECEIVED
SEP 20 1991
OCS
HOBBY OFFICE