

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31707
5. Indicate Type of Lease	STATE ☒ FEE
6. State Oil / Gas Lease No.	B-155
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	78
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4005'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL GAS WELL OTHER Water Injection
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator PO BOX 3109, MIDLAND, TX 79702
4. Well Location BHL: EAST 2491 FNL, 1127 FNL, Sec 36
West 2489 FNL, 853 FEL, Sec 35
Unit Letter E 2491 Feet From The North Line and 127 Feet From The West Line
Section 36 Township 17S Range 34E NMPM Lea COUNTY

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ HORIZONTAL COMPLETION

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-01-00: MIRUSU. TIH W/135 JTS 2 7/8" TBG TO 4252'. 9-02-00: SCRAPE CSG WALL 5700-5800. TIH W/CIBP TO 5770 & SET. TIH W/PKR & SET FR 5757-5760. TIH W/GYRO TOOL. 9-03-00: NDBOP. INSTL TBG FLANGE. 9-06-01: TIH W/WHIPSTOCK. DRILL 5741-5742, 5747, 5750. TOW @ 5741. BOW @ 5747. DRILL 5750-5772, 5803, 5840, 5845, 5971, 6086, 6118, 6133, 6213, 6221, 6245, 6270, 6339, 6371, 6381, 6434, 6444, 6560, 6570, 6656, 6679, 6750, 6775, 6831. TD EAST LATERAL @ 1800 HRS 9-08-00. 9-10-00: TIH W/RBP & SET @ 5722. TEST TO 800 PSI. DUMP 5' SAND ON TOP. TOP OF SAND @ 5717. MILL 5705, 5706, 5711, 5714. UPPER WEST LATERAL TOW @ 5705, BOW @ 5711. DRILL 5714-5746, 5770, 5790, 5998, 6029, 6061, 6092, 6124, 6156, 6166, 6191, 6199, 6213, 6219, 6266, 6313, 6328, 6376, 6390, 6440, 6455, 6503, 6518, 6555, 6560, 6598, 6604, 6734, 6758, 6828. TD 4 3/4" HLE @ 0430 HRS ON 9-13-00. 9-14-00: TIH ON DP W/RBP & SET @ 5600'. RIG RELEASED @ 1800 HRS ON 9-13-00. 9-19-00: TIH W/177 JTS TBG (5529') 9-20-00: TIH & LATCH ONTO RBP @ 5607. REL PLUG & EQUALIZE. TAG SAND @ 5728. TIH W/BAKER HEAD & 184 JTS TBG. TAG TOP OF RBP @ 5733. LATCH ONTO PLUG & REL. TIH W/OPEN ENDED TBG TO 655'. 9-22-00: TIH W/REMAINING 3 1/2" TBG, PKR & 2 7/8" TBG. PKR SET @ 5593. 9-23-00: ACIDIZE LOWER LATERAL W/25,000 GALS 15% HCL & 20,000 GALS WF130. 9-26-00: SET RBP @ 5730. DUMP 1 SX SAND ON TOP OF RBP. TOP OF SAND @ 5723. SET PKR @ 5593. 9-28-00: ACIDIZE W/20,000 GALS 15% HCL & 20,000 GALS WF130. 9-30-00: REL PKR. 10-01-00: TIH W/3 1/2" TBG. PUMP FW DN BACKSIDE TO 400 PSI. C/O SAND FR 5723-5730. 10-03-00: TIH W/3 1/2" TBG & RETR TOOLS. LATCH ONTO RBP & REL PLUG. 10-04-00: TIH W/PKR & TBG. NDBOP. CIRC 110 BBLs OF PKR FLUID. SET PKR & TEST TO 500 PSI FOR 30 MINUTES. CHART ATTACHED. BTM OF PKR @ 5631. FINAL REPORT

Dring 1180 BWPD @ 2000 PSIG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 11/3/00

Telephone No. 915-688-4752

TYPE OR PRINT NAME J. Denise Leake

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

JAN 24 2002

DeSoto/Nichols 12-93 ver 1.0

JCSN

